PDFlib PLOP: PDF Linearization, Optimization, Protection

Page inserted by evaluation version www.pdflib.com – sales@pdflib.com

START 3

Superfund Technical Assessment and Response Team 3 – Region 8



United States
Environmental Protection Agency
Contract No. EP-W-05-050

Technical Memo - Final Removal Site Assessment for Mogul and Grand Mogul Mine Dumps

Mogul and Grand Mogul Mine Site Silverton, San Juan County, Colorado

TDD No. 1005-04

March 21, 2012



In association with:

Garry Struthers Associates, Inc. LT Environmental, Inc. TechLaw, Inc. Tetra Tech EMI TN & Associates, Inc. URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Revision: 2 Date: 03/2012 Page i of iv

TECHNICAL MEMO – FINAL Removal Site Assessment for Mogul and Grand Mogul Mine Dumps

MOGUL AND GRAND MOGUL MINES Silverton, San Juan County, Colorado

EPA Contract No. EP-W-05-050 TDD No. 1005-04

> Prepared By: Joe Gilbert, PG Cordel Schmidt, PG Project Manager

URS Operating Services, Inc. 999 18th Street, Suite 900 Denver, CO 80202-1908

Approved:	Steve Way, On-Scene Coordinator, EPA, Region 8	_ Date:			
	Steve way, Oil-Scene Cooldinator, EFA, Region 8				
Approved:	Charles W. Baker, START 3 Program Manager, UOS	Date:			
Approved:	Cordel Schmidt, PG, START 3, UOS	Date:			

This document has been prepared for the U.S. Environmental Protection Agency under Contract No. EP-W-05-050. The material contained herein is not to be disclosed to, discussed with, or made available to any person or persons for any reason without prior express approval of a responsible officer of the U.S. Environmental Protection Agency. In the interest of conserving natural resources, this document is printed on recycled paper and double-sided as appropriate.

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050 Mogul and Grand Mogul – Technical Memo Distribution List

Revision: 2 Date: 03/2012 Page ii of iv

DISTRIBUTION LIST

U.S. ENVIRONMENTAL PROTECTION AGENCY

Steve Way (2 copies) On-Scene Coordinator, EPA Region 8

URS OPERATING SERVICES, INC.

Cordel Schmidt Project Manager, START 3, EPA Region 8

File (2 copies) START 3, EPA Region 8

Date: 3/2012 Page iii of iv

TECHNICAL MEMO – FINAL Removal Site Assessment for Mogul and Grand Mogul Mine Dumps

MOGUL AND GRAND MOGUL MINES Silverton, San Juan County, Colorado

TABLE OF CONTENTS

		Page #
DIST	NATURE PAGE TRIBUTION LIST LE OF CONTENTS	i ii iii
1.0	INTRODUCTION	1
2.0	SITE ACTIVITIES	1
3.0	BACKGROUND 3.1 Mogul Mine 3.2 Grand Mogul Mine	2
4.0	WASTE ROCK PILES 4.1 Mogul Mine Pile 4.2 Grand Mogul Mine Piles 4.2.1 Waste Rock Pile 1 4.2.2 Waste Rock Pile 2 4.2.3 Waste Rock Pile 3	3
5.0	VOLUME ESTIMATION	6
6.0	WATER PARAMETERS AND SAMPLE COLLECTION	7
7.0	WASTE ROCK SAMPLING	8
8.0	METALS LOADING 8.1 Grand Mogul Mine 8.2 Mogul Mine 8.3 Cement Creek Below the Mogul and Grand Mogul Mines	9
9.0	POTENTIAL REPOSITORY SIGHTING	12
10.0	OBSERVATIONS	13
11.0	LIST OF REFERENCES	15

Mogul and Grand Mogul Mines – Technical Memo Table of Contents

Revision: 2 Date: 3/2012 Page iv of iv

TABLE OF CONTENTS, cont.

TABLES

Γable A	Volume Estimates – Waste Piles
Гable В	Field Parameters - June 2010
Γable 1	Surface Water Sample Results - June 2010
Γable 2	Metal Results for Waste Rock Samples EPA
Γable 3	Chemical Data Analysis - June 2010

FIGURES

Figure 1	Site Location
Figure 2	Site Features
Figure 3	Mogul Field Parameters
Figure 4	Grand Mogul Field Parameters
Figure 5	Potential Repository Location

APPENDICES

Appendix A Photo Documentation

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 1 of 25

1.0 <u>INTRODUCTION</u>

URS Operating Services, Inc. (UOS) Superfund Technical Assessment and Response Team 3 (START)

has been tasked by the U.S. Environmental Protection Agency (EPA), Region 8, under Technical

Direction Document (TDD) # 1005-04, to conduct field activities at the Mogul and Grand Mogul Mines

(CERCLIS ID No. CON000802803) in Silverton, San Juan County, Colorado. Fieldwork for this

Technical Memo was performed in June and July 2010.

This Technical Memo provides a summary of information collected during the site activities. It has been

prepared in accordance with TDD No.1005-04. Activities were performed in accordance with the "UOS

Generic Quality Assurance Project Plan" (QAPP) (UOS 2005).

2.0 <u>SITE ACTIVITIES</u>

Site visits to the Mogul and Grand Mogul mines were conducted during June 14 - 16 and July 21

- 22, 2010 (Figure 1). The purpose of the site visit was to gather information needed to evaluate

ongoing releases of mine water and acid rock drainage and to assess potential options to mitigate

those releases. The primary focus of these investigations was to assess the waste rock dumps in

terms of contribution to the releases to Cement Creek. Laboratory analysis was performed by the

TestAmerica Laboratory in Arvada, Colorado. Photo documentation is provided in Appendix A.

Site tasks included:

Record physical and chemical parameters of surface water flows and collect surface water

samples near the Mogul and Grand Mogul Mine waste piles to assess surface water and waste pile

interactions.

Characterize waste rock piles identified by the Bureau of Land Management (BLM) and the U.S.

Geological Survey (USGS), and estimate waste pile volumes and surface areas.

Performing test pit investigations to assess potential adit drainage, infiltration, and groundwater

flows into and out of the Mogul and Grand Mogul waste piles.

Perform GIS data gathering and ground-truthing to field-verify a potential repository sighting

analysis.

Date: 03/2012 Page 2 of 25

3.0 BACKGROUND

Four main waste piles and associated surface water drainage were assessed during the site visits. One pile

is located at the Mogul Mine site, and three piles are located at the Grand Mogul Mine site (Figure 2).

3.1 MOGUL MINE

The Mogul Mine area is located approximately 11,370 feet above mean sea level (AMSL) and

consists of a waste rock pile and an open adit. The Mogul Mine resides in a small glacial

depression adjacent to Cement Creek bounded by talus, solifluction deposits, and bedrock

outcrops. Cement Creek flows to the north of this depression (Figure 2). Shallow soils have

developed within the basin. To the west, or down gradient of the Mogul Mine, a relatively flat

saturated area receives surface and shallow groundwater from seeps and springs. Surface water is

channeled along the northeast side of the saturated area, and this channel drains to Cement Creek.

An access road passes through the Mogul Mine site area. Though narrow, it is suitable for high

clearance vehicles and track-mounted excavation equipment.

The Mogul Mine adit is open and flows approximately 0.138 cubic feet per second (cfs) (62

gallons per minute [gpm]) as measured by EPA in June of 2010. A Parshall flume has been

installed to monitor adit effluent which is channeled to the south of the main waste rock pile. A

small corrugated metal shed is present on top of the Mogul Mine waste rock pile near the adit.

Some scattered mine-related debris including wood material exists at the site; however no

significant cultural debris appears to be present.

3.2 GRAND MOGUL MINE

The Grand Mogul Mine site is up-valley and east of the Mogul Mine site at approximately 11,680

feet AMSL. Access to the Grand Mogul Mine is via a four wheel drive road that bisects the

Mogul Mine site and, more indirectly, via an access road that traverses the north wall of the basin

above the mine (Figure 2). At the time of the site visit in June, a large snowfield covered the

eastern portion of the basin. Shallow soils and alpine tundra typify the Grand Mogul basin. Basin

walls are bounded by steep talus, bedrock outcrops, and solifluction deposits. The Grand Mogul

Mine includes three waste rock piles (numbered piles 1, 2, and 3, Figure 3) that are spaced

throughout the upper Cement Creek basin.

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012

Page 3 of 25

There does not appear to be an adit associated with Pile 1; its morphology and location suggest

that this pile may have been transported from other mine workings to its current location. A grate-

covered underhand stope is exposed approximately 60 feet to the north of Pile 2. Small amounts

of cultural debris are scattered throughout the basin; however, no significant mine workings aside

from the stope at Pile 2 are evident.

4.0 WASTE ROCK PILES

> 4.1 MOGUL MINE PILE

The Mogul Mine site area includes one large waste rock pile (Figure 3, Photo 1). The waste rock

pile is bisected by a four-wheel-drive access road into two tiers (Figure 2). The upper tier (Tier

1) consists of multiple lobes of primarily sulfide-bearing and vein-derived quartz waste rock. The

tier appears to have supported narrow-gauge ore rails although no cultural debris or rail debris

was observed on the waste rock pile. The maximum thickness of Tier 1 is estimated at 30 feet,

based upon field observation. Grain sizes within the tier range from silty to coarse-grained sand

including cobbles and boulders up to approximately 20 inches in diameter. Surface water flow at

the base of Tier 1 was visually estimated at 0.02 cfs (10 gpm) at the time of the June site visit.

Adit water from the Mogul Mine has been directed around the south side of the waste rock pile in

order to sequester flow and prevent infiltration into the main rock pile. The adit discharge is

contained in a rubberized plastic channel for approximately half of the distance downslope of the

waste rock pile. From there it joins other basin discharge, is channeled, and enters Cement Creek.

The lower tier (Tier 2) of the Mogul Mine waste rock pile consists primarily of sulfide-bearing

and vein-derived quartz rock. Several outcrops of bedrock were observed in the lower tier, which

suggests that the overall thickness of the lower tier may be shallow relative to the upper tier

(Photo 5). A small spring was observed issuing from the base of Tier 2, visually estimated at 2 to

3 gpm.

An approximately 100-foot-long trench was excavated for geologic observation along the

northeastern boundary of Tier 1 on July 22 (Figure 2). The westward-to-eastward transecting

trench was excavated to a depth of 9 feet below ground surface (bgs) where bedrock was

encountered. The eastern extent of the excavation was located near the adit portal. A horizontal

distance of 20 feet was maintained between the trench and the portal to minimize potential

impacts to the portal. Excavated materials were returned to the trench following geological

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 4 of 25

logging, and the excavator was used to compact the material during replacement. Photo 19 shows

the excavated area following material replacement.

Water was observed entering the trench in the eastern corner closest to the portal. The rate of

inflow was visually estimated at 2 gallons per minute. The water pooled in the base of the

excavation. Photo 18 shows the excavation profile where the spring was observed. Two waste

rock samples, MMWR01 and MMWR02, were obtained from excavated material derived from

the western and eastern ends of the trench, respectively. Samples were submitted for

geotechnical and chemical analysis; results are presented in Table 2.

As part of the investigation for a potential repository location two test pits, Test Pit 1 and Test Pit

2 (Figure 2), were also excavated in an area adjacent to the mine dump. The depth of the test pits

was limited by the presence of shallow bedrock with Test Pit 1 excavated to a depth of 7 feet bgs,

and Test Pit 2 was excavated to 5 feet bgs. Water was not observed in either pit. Sample

MMTP01was obtained from Test Pit 1 for geotechnical and chemical analysis. No sample was

collected from Test Pit 2 as the observed lithology was similar to that of Test Pit 1. Mine

workings were not disturbed during these excavations and care was taken to restore conditions to

those existing prior to excavation. Photos 20 through 23 show Test Pit details.

4.2 GRAND MOGUL MINE PILES

The Grand Mogul Mine area contains three main waste rock piles; Pile 1, Pile 2, and Pile 3 (Table

A, Figure 4). The piles are located along a west to east transect up-basin with pile 2 located

approximately 500 feet beyond pile 1, and pile 3 approximately 250 feet beyond pile 2.

4.2.1 Waste Rock Pile 1

Waste Rock Pile 1 is the smallest of the three piles at Grand Mogul and consists of a

single pile with a visually estimated maximum thickness of 15 feet (Table A, Photo 12).

Waste Rock Pile 1 is also referred to in BLM reporting as the "Lower Waste Pile" (BLM

2006). This pile is flat-lying and is contained within a small tributary channel of Cement

Creek. Materials encountered in this pile consisted of mineralized waste bedrock and

sulfide-bearing and vein-derived quartz. A small spring emanated from the down gradient

base of this pile and had an estimated discharge of approximately 1 gpm on June 16 in a

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 5 of 25

westward direction. Grain sizes of waste rock within the rock pile consist of silty to

coarse sand and waste rock cobbles up to approximately 12 inches in diameter.

4.2.2 Waste Rock Pile 2

Grand Mogul waste rock Pile 2 is referred to as the "Grand Mogul Stope Complex" by

the BLM (BLM 2006) (Table A, Photos 10, 11, and 15). It consists of two large lobes of

mineralized waste rock that lie beneath the four-wheel drive access road (Figure 4).

Immediately to the north of the waste rock piles is an underhand mine stope that is

covered with a large safety grate. The maximum thickness of the two main waste rock

pile lobes is estimated at 25 feet. Grain sizes of waste rock within the two lobes consist of

silty to coarse sand and waste rock cobbles up to approximately 12 inches in diameter.

Surface water was observed flowing from Pile 3, and past the toe of Pile 2 (Figure 4).

Additional input from a seep within Pile 2 may contribute to this flow but it was not

discernable during field observation. Surface water flow near the base of Pile 2 was

visually estimated on June 16 at approximately 20 gpm to the south and west.

A third test pit, Test Pit 3, was excavated to 4 feet bgs east of the Grand Mogul Mine

Waste Rock Pile 2 to determine the depth of cover in the area adjacent to the pile (Figure

4). No water was observed in this pit. Soil materials sample MMTP02 was obtained from

this pit for geotechnical and chemical analysis. Care was taken to restore site conditions

to those prior to excavation.

4.2.3 Waste Rock Pile 3

Waste rock Pile 3 is the largest of the Grand Mogul Mine piles (Table A) and, at the time

of the site visit, its northwestern and northeastern flanks were partially covered with

snow. The pile consists of a large multi-lobe pile and a smaller eastern lobe (Figure 4)

(Photos 9, 13, and 16). The waste rock pile is typified by mineralized bedrock cobbles

with grain sizes ranging between fine sand and pea-gravel-sized waste rock. Large

cobbles of waste rock are also present within, and on top of the pile. A spring flowing to

the south and west at an estimated rate of 12 gpm on June 16 was observed issuing from

the toe of Pile 3.

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 6 of 25

A second trench (Trench 2, Figure 4) was excavated on July 22 into the northeastern

extent of the pile in an attempt to discern the location of a possible collapsed adit portal

and assess the presence of other seeps entering the waste pile along this edge (Photo 27).

The east-to-west transecting trench was excavated in two phases, the first extending 25

feet to the southwest of the suspected location of the mine adit, to a depth of 15 feet.

Bedrock was encountered at the bottom of the excavation along its entire length. Waste

rock and natural talus were encountered along the trench with waste rock being prevalent

in the eastern 15 feet, and then natural rock being encountered along the remaining 10

feet. The trench walls began to fail when talus was encountered and, at this point the

excavation was terminated. A seep was encountered on the northern wall of the

excavation. The seep was observed at between 4 and 8 feet bgs and was approximately 4

feet in width. Discharge from the seep was visually estimated to be less than 1 gpm.

Further investigation of this location was not undertaken due to the instability of the talus

slope adjacent to the excavation.

The second phase of the trench was extended an additional 85 feet toward the west for a

total trench distance of 110 feet. No seeps were encountered along this western extent;

talus was encountered along the trench from 35 feet to 110 feet. Depth to bedrock was

approximately 15 feet bgs at the east origin, reducing to approximately 8 feet bgs at the

northwestern extent.

No mining structures were encountered or disturbed during the excavation. Excavated

materials were replaced and compacted using the weight of the excavator.

5.0 **VOLUME ESTIMATION**

Volumes for the Mogul and Grand Mogul waste piles were estimated using data gathered during the site

visits and were analyzed in a Geographic Information System (GIS). During the site visit, the salient lobes

and thickest portions within each waste pile were identified, their central points were located with a

Differential Global Positioning System (DGPS), and their thicknesses at their highest point were

estimated. The boundary of the waste rock pile was also surveyed using a DGPS in order to provide area

estimates and a base footprint for each waste pile. DGPS measurements were converted to a three

dimensional (3D) surface, a convex hull in a GIS. GIS 3D spatial analyst was then used to summarize the

interior volume of the convex hull, and to determine its 3D surface area. The two dimensional (2D)

Date: 03/2012 Page 7 of 25

footprint was also calculated from DGPS data and was summarized in the same GIS. Waste rock volumes and areas are presented in Table A. BLM estimates obtained in 2006 are also included.

TABLE A
Volume Estimates – Waste Piles*

Mine	Pile Number	BLM* Name	3D Surface Area (ft²)	Footprint Area (ft²)	Volume (yds³)	BLM* Volume (yds³)
Mogul	1		106,068.5	101,590.6	41,374.7	
Grand Mogul	1	Lower Waste Pile	8,449.7	4,187.2	845.0	
Grand Mogul	2	Stope Complex	22,539.8	19,751.9	6,925.9	8,000
Grand Mogul	3	Eastern Waste Pile	42,754.6	39,041.0	18,750.2	9,000

^{* &}quot;Removal Preliminary Assessment Report, Grand Mogul Mine, Silverton, CO" BLM 2006

6.0 WATER PARAMETERS AND SAMPLE COLLECTION

During the site visit in June 2010, field water parameters were collected at various points upgradient and down gradient of all waste rock piles to determine any influence by the waste rock on surface water discharge. Field parameters gathered during the site visit are included on Figures 3 and 4 and summarized in Table B.

Three water samples were collected at the Mogul Mine site and analyzed for total and dissolved metals by the TestAmerica Laboratory in Arvada, Colorado, using Inductively Coupled Plasma Mass Spectrometry (ICP-MS) and atomic emission spectroscopy (AES) analyses (Table 1). Sample locations included a waste rock seep below the toe of the pile (sample MMSW01), Mogul Mine adit flow at the toe of the pile (sample MMSW02), and Mogul Mine adit flow from a mid-point location on the pile (sample MMSW03). These water samples are compared to water samples from the same watershed, also collected in June of 2010 during a separate sampling event (Table 1).

TABLE B Field Parameters – June 2010

Location	pН	Conductivity (mS/m)	Temp °C	Est. Flow Rate (gpm)
MMSW01. Mogul mine waste rock Seep below toe of pile	3.82	56.9	12.90	10
MMSW02. Mogul mine adit flow at	4.01	82.0	10.50	3

ft² – square feet

yds³ – cubic yards

Date: 03/2012 Page 8 of 25

TABLE B Field Parameters – June 2010

Location	pН	Conductivity (mS/m)	Temp °C	Est. Flow Rate (gpm)
toe of waste pile				
MMSW03. Mogul mine adit flow at mid waste rock pile	4.50	81.4	10.40	10
Mogul Adit	4.61	96.9	7.50	62
Grand Mogul Pile 1 spring	4.78	15.7	10.20	1
Cement Creek Confluence	5.21	16.8	8.10	1,000
Surface Water near Grand Mogul Pile 2	3.86	16.6	11.30	20
Grand Mogul Pile 3 spring	3.92	14.6	8.90	12
Cement Creek Upgradient	5.38	11.5	8.40	1,000
Mogul Toe	2.67			3

gpm - gallons per minute

mS/M = milliSiemens per meter

*Parshall Flume Measurement, EPA June 2010

-- Not collected

7.0 WASTE ROCK SAMPLING

Mine dump waste rock samples were obtained in 1996, 1997, and 2010 at the Mogul and Grand Mogul mines (UOS 2009, USGS 2007). Specific sample locations on the waste rock piles are unknown. Table 2 includes metals concentrations and Synthetic Precipitation Leaching Procedure (SPLP) laboratory analysis from those sampling events. For ease of presentation the following discussion is based upon zinc observations. Other metals that are present on site share similar relationships.

SPLP samples in Table 2 provide a value that represents the potential leachable concentration from the material being analyzed. Total Metals laboratory results presented in Table 1 indicate a release of metals to surface water flows. For example; The SPLP concentration of zinc at the Grand Mogul Pile 3 is 10,000 micrograms per Liter (μ g/L). During the June 2010 sampling event (Table 1), a Total Metal concentration of 3,350 μ g/L of zinc was observed in a seep releasing from the Grand Mogul Pile 3 (sample CC01C). A water sample hydraulically upgradient of the Grand Mogul mine (sample CC01F, Table 1) revealed a zinc concentration of 379 μ g/L, nearly 9 times less than the amount observed in the Grand Mogul pile 3 seep, and 26 times less than the observed SPLP leachable amount of 10,000 μ g/L.

Uncertainties exist as to the provenance of the water at CC01C. The water flowing at this location may be from a collapsed mine adit that is flowing in the shallow subsurface, or it may be ground or other surface water that is interacting with Pile 3 itself.

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 9 of 25

......

Inductively Coupled Plasma - Atomic Emission Spectroscopy (ICP-AES) laboratory analysis (Table 2)

indicates total amounts of metals within the material being analyzed. ICP-AES zinc values at the Grand

Mogul Pile 3 ranged from 30,000 to 34,000 mg/kg. Mogul Mine values for zinc ranged from 5,800 to 279

mg/kg. Lead values ranged from a maximum of 24,400 mg/kg at the Mogul Mine to a minimum of

24,000 mg/kg at Grand Mogul Pile 3.

8.0 <u>METALS LOADING</u>

Comparisons between START and EPA data collected during June 2010 sampling events show that both

the Grand Mogul and Mogul mines are impacting Cement Creek at specific sample locations (Tables 1, 2

and 3, Figures 3 and 4). However, the data set represents a "snapshot" in time and may not represent

perennial conditions. For ease of presentation the following discussion is based upon zinc observations.

Other metals that are present on site share similar relationships.

Table 3 includes selected samples and analytes (CC01F to CCOPP-12) which are presented in an order

that represents an upgradient toward down gradient profile within the Cement Creek basin near the Mogul

and Grand Mogul mines. In the table, the location type describes the location of the sample relative to

Cement Creek. The term "Feature" refers to samples that were taken from surface water near or derived

from mine features while "Cement Creek" refers to samples that were collected directly from Cement

Creek. In the following discussion, "below" refers to a sample or feature that is located down gradient and

downstream in its relation to other features, and "above" refers to a sample or feature that is located

upgradient and upstream in its relation to other features. These data represent conditions observed in the

Cement Creek watershed for June 2010.

For the purposes of this discussion, Cement Creek sample CC01F; upgradient of the Mogul and Grand

Mogul mines was established as a background sample. The sample results from this location establish

water quality conditions of Cement Creek prior to interaction with either Mogul or Grand Mogul mine-

related features. Metals water loading calculations were determined by the equation [ppd = μ g/L

(cfs)(.00539)] where μ g/L = micrograms of metals content per liter of water, cfs = water flow measured in

cubic feet per second, while the constant 0.00539 was established to convert the results to pounds per day

(ppd).

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 10 of 25

8.1 GRAND MOGUL MINE

The Grand Mogul Mine is upgradient of the Mogul Mine. The most upgradient features at the

Grand Mogul Mine are Piles 3 and Pile 2 (Figure 4). Subtracting background sample CC01F from

CC01H shows the relationship between Pile 3 and Pile 2. Data contained in Table 3 show that

24.5 pounds per day (lbs/day) of zinc enters Cement Creek between Sample locations CC01F and

CC01H. Furthermore, the overall concentration of zinc in Cement Creek increases from 370

μg/L at CC01F to 1,120 μg/L at CC01H, which is approximately 400 feet below Grand Mogul

Pile 2.

No waste rock seep was observed emanating from Pile 2 and, therefore, the primary source for

the increase in zinc at CC01H is likely from Pile 3. It is possible that the discharge observed

during trenching activities was issuing from a collapsed adit; this water interacts with the waste

rock piles before discharging from the toe of Pile 3. The discharge rate observed in the trench was

lower than that of the toe, indicating that other sources of water are entering the pile, or that there

may be different flow paths within the waste pile material. Given the current dataset, it is not

possible to determine how the water chemistry of the seep is affected by interactions with the

waste rock pile.

Cement Creek combines with the unnamed tributary below Grand Mogul piles 2 and 3 (Figure 4).

Sample CC01T documents the observed change in Cement Creek after its confluence with the

unnamed tributary: flow rate increases by 2.68 cubic feet per second (cfs), overall zinc loading

increases by 9 lbs/day, and overall zinc concentration decreases from 1,120 μg/L to 978 μg/L.

These data suggest that while Cement Creek contributes a load increase of approximately 30

percent before its confluence with the unnamed tributary, it has an overall diluting effect on zinc

concentrations on the unnamed tributary flow that enters it.

Sampling was not performed in Cement Creek immediately below Grand Mogul Pile 1 during

these events. It is, therefore, not possible to determine the direct effect of Grand Mogul Pile 1 on

the concentration or load in Cement Creek. However, its contribution to these factors is likely

small due to low flow rates observed near the pile (0.016 gpm – average recorded during August

and September of 2009), relatively low concentration value (1,290 µg/L), and low zinc load

(estimated 0.11 lbs/day) relative to other mine features (Tables 1 and 3). Comparisons of zinc

loading in Cement Creek between Mogul Mine features and Grand Mogul Pile 1 further indicate

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 11 of 25

that Grand Mogul Pile 1 does not contribute significantly to the load and concentration of zinc in

Cement Creek (Table 3).

In summary, the increase in zinc loading to Cement Creek from the Grand Mogul Mine piles 2

and 3 is 24.51 lbs/day and the concentration within Cement Creek increases 750 μg/L.

8.2 MOGUL MINE

Mogul Mine consists of an open and flowing mine adit and associated waste rock pile (Figure 3).

Several ephemeral seeps and other flowing mine features exist along the southern flank of the

valley (Figure 2).

The feature at the Mogul Mine with the largest recorded flow rate (0.138 cfs, or 62 gpm) during

the June sampling event performed by START and the EPA is the mine adit itself (sample

location CC02D). Mine adit water also contains the largest concentration of zinc observed in the

Mogul Mine area (22,900 μg/L) and contributes the largest zinc load of all surface water features

observed and sampled during the June sampling event (17.05 lbs/day).

The location of sample MTD-3 is below the observed mine adit flow. All seeps that appear to

interact with the Mogul Mine waste rock pile appear to be channelized at this location, including

the adit flow itself (CC02D). Therefore, MTD-3 is assumed to encapsulate surface water flows

that either emanate from or interact with mine features. This sample location represents the

surface water characteristics prior to drainage into Cement Creek. With an observed flow rate of

0.394 cfs (177 gpm) water flowing at MTD-3 contributes a zinc load of 17.41 lbs/day and a zinc

concentration of 8,190 µg/L (Table 3).

Seeps issuing from the waste rock were observed and sampled at location MTD-1 and at

MMSW01 (Table 3). Though these samples contain elevated loads and concentrations of zinc,

they represent approximately 1 to 10 percent of the load observed at MTD-3. The concentration

of zinc decreases between the mine adit and MTD-3, suggesting that the waste rock seeps at

MTD-1 and MMSW01 contribute additional surface water, but limited amounts of zinc.

The overall surface water concentrations at MTD-3 suggest that seeps interacting with the waste

rock do not exhibit a significant increase in metals concentrations, and other subsurface flows are

diluting zinc within the adit flow, ultimately indicating that the waste rock pile contributes little

concentration and load to the surface flow that enters Cement Creek. The mine adit flow itself

Date: 03/2012 Page 12 of 25

appears to be the prime contributor of metals load from the Mogul Mine. Uncertainties exist in this interpretation as this data does not account for any water inputs to Cement Creek (surface or subsurface) that are not encapsulated by the channel at MTD-3.

8.3 CEMENT CREEK BELOW THE MOGUL AND GRAND MOGUL MINES

Conservative estimates of zinc loading to Cement Creek from the Grand Mogul mine were calculated based on stream flow measurements and zinc concentrations from sample locations CC01H (basin flow from piles 2 and 3), and CC02i (pile 1 drainage) which indicate that 24.62 lbs/day are loading into Cement Creek from the Grand Mogul mine area. This calculation excludes 9.2 lbs/day of measurable zinc load from upstream sample location CC01F. A zinc load from the Mogul mine of 17.41 lbs/day was estimated based on data from-location MTD-3 below the Mogul mine complex, prior to discharge into Cement Creek.

Therefore an estimated zinc load-of 42.03 lbs/day to Cement Creek can be attributed to the Grand Mogul and Mogul mines. This amount is equal to 44 percent of the total zinc load (96.61 lbs/day) measured in Cement Creek at sample location CCOPP-12 approximately 1 mile down gradient of the Mogul mine. It is likely that the total metals loading from the Grand Mogul and Mogul mines is not fully accounted for due to diffuse flow of contaminated groundwater into Cement Creek. The contaminated groundwater results from infiltration of rain and snow, with high dissolved metals resulting in the vicinity of the grand mogul and mogul mines as well as possible subsurface discharge of mine water to Cement Creek.

9.0 POTENTIAL REPOSITORY SIGHTING

Prior to the site visit, a preliminary basin model for potential repository delineation was created using existing published data sets from the Cement Creek watershed. During the site visit, an area that met suitable criteria for a repository was outlined and identified (Figure 5). This area is to the northwest of the Mogul Mine and is coincident with the preliminary basin model.

The repository area is 3.8 acres in size and has a slope of less than 20 percent. Existing roads already intersect the site. The repository is within 100 feet of most of the Mogul Mine waste pile. Shallow soils have developed in the repository site area and may provide favorable borrow source and/or capping material for repository engineering considerations. The repository is within 300 feet of Cement Creek;

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 13 of 25

however, it may be possible that not all of the repository area would be utilized for waste consolidation

and disposal.

A preliminary GIS analysis that combines several datasets in a qualitative ranking system was performed.

To complete the analysis, data are assigned a numeric value and then mathematically multiplied to the

overall model. High values represent areas with most favorable characteristics. For example, in the

repository model, areas closer than 300 horizontal feet to existing surface water are less favorable for a

repository, as placing waste rock this close to water increases the risk of mine waste adversely affecting

surface water. A dataset was created in which any area closer than 300 feet to known surface water is

assigned a value of 1. Any area farther than 300 feet is assigned a value of 2. The value 1 is less favorable

than the value of 2. In a like manner, other thematic data (detailed below) is assigned numeric values.

After all datasets are assigned values, the areas are multiplied together. High values within the data

represent areas of most favorable characteristics for the location of a waste repository.

This model combines the following criteria to isolate a portion of the Cement Creek watershed for

favorable repository locations (USGS 2002, Gesch 2007, Gesch et al. 2002):

Elevation – The National Elevation Dataset (NED) 10-meter Digital Elevation Model (DEM) was

used to derive local elevations.

• Slope – Slopes greater than 20 percent were not considered.

• Roads – Areas close to existing mine roads were considered more favorable.

• Surface Water – Areas within 300 feet of existing surface water were considered less favorable.

• Geology – Bedrock geology was considered most favorable while talus and other geologically

young rock units were less favorable.

Structures – Areas within 300 feet of previously mapped faults and large geologic structures were

considered less favorable.

10.0 <u>OBSERVATIONS</u>

The following summary is presented for both surface water and waste rock data collected from Mogul and

Grand Mogul Mines. The conclusions are based upon conditions of surface water and mine waste

observed at these mines in June 2010. These conclusions and observations do not consider seasonal

variation.

TDD No. 1005-04

T:\START3\Mogul and Grand Mogul\1.0 Deliverables\Technical_memo\Technical Memo - Revision 2\TextTechnical Memo - Revision 2.doc

URS Operating Services, Inc. START 3, EPA Region 8 Contract No. EP-W-05-050

Date: 03/2012 Page 14 of 25

• The Grand Mogul Mine contributes a significant increase of metals as compared to upstream

sample concentrations. For example, zinc concentrations in Cement Creek increase from 370

ug/L above the mine to 1,070 ug/L below Piles 2 and 3 (the main waste rock dump). It is likely

that the majority of this load comes from Grand Mogul Pile 3, which likely includes subsurface

flows interacting with waste rock.

• Cement Creek enters the basin below Grand Mogul Piles 2 and 3, and at the time of this

sampling, it was carrying a zinc load of 14.49 lbs/day and a concentration of 1,070 μg/L.

It is unlikely that Grand Mogul Pile 2 contributes significant amounts of zinc to Cement Creek as

no surface water was observed interacting with the pile and flowing into Cement Creek.

• Grand Mogul Pile 1 does not appear to contribute significant amounts of zinc to Cement Creek.

• Mogul Mine waste rock contributions to the metals load in Cement Creek appear to be small as

indicated by concentrations and flow observed at surface water runoff features below the Mogul

Mine sample location, e.g., sample MTD-3. As much as 95% of the load observed at MTD-3 may

come from the Mogul Mine Adit discharge. Conditions during high flow run-off events may

temporarily increase the relative load from the waste dump. Trenching performed in the top of

waste dump showed that only a minor amount of subsurface seepage. It does not appear that the

dump is contributing much metals loading.

Combined, the Mogul and Grand Mogul mines contributed a significant portion of the overall

zinc load to upper Cement Creek above location CCOPP-12 in June 2010.

Additional tributaries enter Cement Creek between the Mogul and Grand Mogul mines and the

downstream sampling point CCOPP-12, approximately 1 mile down stream. These tributaries

and/or other sources were contributing 56 percent of the overall zinc load on Cement Creek at

CCOPP-12.

Date: 03/2012 Page 15 of 25

11.0 <u>LIST OF REFERENCES</u>

Bureau of Land Management (BLM). 2006. "Removal Preliminary Assessment Report, Grand Mogul

Mine, Silverton, CO." BLM National Science and Technology Center. November 2006.

Gesch, D.B., 2007, The National Elevation Dataset, in Maune, D., ed., Digital Elevation Model

Technologies and Applications: The DEM Users Manual, 2nd Edition: Bethesda, Maryland, American

Society for Photogrammetry and Remote Sensing, p. 99-118.

Gesch, D., Oimoen, M., Greenlee, S., Nelson, C., Steuck, M., and Tyler, D., 2002, The National Elevation

Dataset: Photogrammetric Engineering and Remote Sensing, v. 68, no. 1, p. 5-11.

U.S. Geological Survey (USGS). 2002. "Generalized Geologic Map of Part of the Upper Animas River

Watershed and Vicinity, Silverton, Colorado. Douglas B. Yeager and Dana J. Bove. Miscellaneous Field

Studies Map MF-2377.

U.S. Geological Survey (USGS). 2007. Integrated Investigations of Environmental Effects of Historical


Mining in the Animas River Watershed. San Juan County, Colorado Professional Paper 1651. Volume 1.


URS Operating Services, Inc. (UOS). 2005. "Generic Quality Assurance Project Plan" for the Superfund

Technical Assessment and Response Team 2, Region 8. June 13, 2005.

URS Operating Services, Inc. (UOS). 2009. "Data Gap Analysis – Revision 2 Upper Animas Mining

District, Cement Creek" October, 2009.





GRAND MOGUL MINES

Figure:


Figure Title: SITE LOCATION

TDD County: SAN JUAN TDD: 1005-04 TDD State: Date: CO 03/2012






Sources: USGS Topographic Map Bing Maps



TDD: 1005-04 Date: 03/2012








TABLE 1 Surface Water Sample Results June 2010

Analyte	Sample ID Location	MMSW01 MM Waste Rock Seep Below Toe of Pile	MMSW02 MM Adit Flow Toe of Waste Pile	MMSW03 MM Adit flow Mid Waste Rock Pile	CC01F Basin Flow Above GM	CC01C Waste Seep From GM Pile 3	CC01H Basin Flow Below GM Piles 2 and 3	CC01S CC between GM Pile 1 and Pile 2	CC01T CC below GM Piles 2 and 3	CC02i Drainage Above CC GM Pile 1	CC02D MM Adit Flow at Flume	MTD-1 Waste Rock Seep Toe of MM Waste Pile	MTD-2 MM Adit flow at Toe of Waste Rock	MTD-3 MM Drainage Above CC	CCOPP-12 Approx 1 mile below MM and GM
Aluminum (μg/L)	Dissolved	4,400	2,200	2,000	<100	1,930	396	1,250	702	715	2,390	1,180	3,360	3,500	470
	Total	4,200	2,200	2,100	248	1,990	698	1,470	1,070	731	2,520	1,180	3,350	3,490	568
Arsenic (µg/L)	Dissolved	< 0.42	< 0.42	0.94J	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0
	Total	0.34J	1.9J	2.8J	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0
Beryllium (μg/L)	Dissolved	1.9J	3.1	2.9	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	3.5	<1.0	1.7	1.2	<1.0
	Total	1.6	3.1	3.2	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	3.6	<1.0	1.6	1.1	<1.0
Cadmium (µg/L)	Dissolved	35	33	33	1.9	14.9	5.5	5.7	5.2	4.2	38.9	12.2	37.1	28.9	3.1
	Total	35	34	34	2.1	15.9	5.1	6.1	5.3	4.5	40.3	11.5	37.3	27.7	3.1
Calcium (µg/L)	Dissolved	58,000	140,000	140,000	18,100	11,800	16,900	25,000	20,700	22,100	168,000	27,100	74,000	43,500	13,000
Chromium (µg/L)	Dissolved	<1	<1	<1	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0
	Total	1.5J	< 0.5	< 0.5	<5.0	<5.0	<5.0	<5.0	<5.0	<5.0	< 5.0	<5.0	<5.0	<5.0	<5.0
Copper (µg/L)	Dissolved	590	43	26	27.2	295	141	57.5	88.4	33.7	22.3	87.9	529	491	56.9
	Total	600	47	26	44.2	292	140	61.5	95	35.8	22.6	85.1	533	485	57
Iron (µg/L)	Dissolved	4,900	8,800	15,000	<100	2,510	<100	<100	<100	144	22,000	395	8,830	4,320	<100
	Total	4,700	11,000	24,000	<100	2,700	752	<100	374	207	26,100	1,450	11,500	5,740	305
Lead (µg/L)	Dissolved	51	140	130	<1.0	36.5	3	2	2.9	2.6	153	31	87.2	45.4	3.1
	Total	50	140	140	11.5	40.2	11.7	3.5	8.3	3.6	168	40.6	98.2	50.6	5
Magnesium (μg/L)	Dissolved	5,200	8,200	8,300	1,740	2,140	1,890	3,720	2,720	2,940	10,200	2,160	5,880	3,800	1,440
Manganese (μg/L)	Dissolved	7,600	20,000	19,000	148	1,670	449	2,170	1,230	76.2	24,100	3,350	10,800	4,970	552
	Total	7,700B	18,000	20,000	157	1,730	455	2,270	1,310	80.1	25,400	3,550	11,400	5,290	585
Nickel (µg/L)	Dissolved	10	11	9.4J	<4.0	<4.0	<4.0	<4.0	<4.0	<4.0	8.8	4.3	7.3	7.5	<4.0
	Total	9.8	11	11	<4.0	4.7	<4.0	5.7	4.1	4.9	12.2	4.9	8.1	8.7	<4.0
Potassium (μg/L)	Dissolved	660J	1,400J	1,600J	<1,000	<1,000	<1,000	<1,000	<1,000	<1,000	1,840	<1,000	<1,000	<1,000	<1,000
Selenium (µg/L)	Dissolved	2.1J	<1.4	<4.9	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	1.4	<1.0	1	<1.0	<1.0
	Total	< 0.7	< 0.7	< 0.7	<1.0	<1.0	<1.0	<1.0	<1.0	<1.0	1.6	<1.0	1.3	<1.0	<1.0
Silver (µg/L)	Dissolved	0.13J	< 0.03	3.4J	<0.5	< 0.5	<0.5	<0.5	< 0.5	< 0.5	<0.5	<0.5	<0.5	<0.5	<0.5
	Total	0.26J	0.093J	0.036J	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	<0.5	< 0.5	<0.5	<0.5	<0.5

Revision: 2 Date: 03/2012 Page 22 of 25

TABLE 1, cont. **Surface Water Sample Results** June 2010

Analyte	Sample ID Location	MMSW01 MM Waste Rock Seep Below Toe of Pile	MMSW02 MM Adit Flow Toe of Waste Pile	MMSW03 MM Adit flow Mid Waste Rock Pile	CC01F Basin Flow Above GM	CC01C Waste Seep From GM Pile 3	CC01H Basin Flow Below GM Piles 2 and 3	CC01S CC between GM Pile 1 and Pile 2	CC01T CC below GM Piles 2 and 3	CC02i Drainage Above CC GM Pile 1	CC02D MM Adit Flow at Flume	MTD-1 Waste Rock Seep Toe of MM Waste Pile	MTD-2 MM Adit flow at Toe of Waste Rock	MTD-3 MM Drainage Above CC	CCOPP-12 Below MM and GM
Sodium (µg/L)	Dissolved	2,500B	4,600B	4,800B	830	569	988	932	1,060	1,140	5,430	1,870	3,000	2,120	622
Zinc (µg/L)	Dissolved	11,000	20,000	19,000	370	3,210	1,120	1,070	978	1,290	22,900	4,400	14,900	8,190	731
	Total	11,000	19,000	20,000	379	3,350	1,110	1,060	1,050	1,290	24,500	4,550	15,400	8,910	735
рН	·	3.82	2.67	4.5	5.72	3.45	5.53	5.13	5.27	3.92	3.58	3.6	3.02	3.15	5.07
Conductivity (mS/cm	1)				129	208	134	205	167	191	785	248	928	604	110
Flow (cfs)		0.02228	0.006684	0.02228	4.61		5.58	2.51	8.26		0.138			0.394	24.5

 μ g/L = Micrograms per liter

ms/cm = MilliSiemens per centimeter

cfs = Cubic feet per second

B = The analyte was detected in the blank

 $CC = Cement \ Creek \qquad GM = Grand \ Mogul \ Mine \qquad MM = Mogul \ Mine \qquad \mu_S$ $J = The \ associated \ numerical \ value \ is \ an \ estimated \ quantity \ between \ the \ detection \ limit \ and \ the \ quantitation \ limit.$

-- = no sample data

Date: 03/2012 Page 23 of 25

TABLE 2 Waste Rock Samples

Sample ID	35B (AN	ILI Mine #35)	35C (AM	LI Mine #35)	CC-SO-06	MMWR01	MMWR02	
Sample Source		GS 2007* btained in 1997		S 2007* tained in 1997	UOS START 2009^ Sample Obtained in 1996	START 2010		
Location Description		nd Mogul Rock Pile 3		d Mogul Rock Pile 3	Mogul Mine Waste Rock Pile	Trench at Mogul Mine	Trench at Grand Mogul Mine Pile 3	
Analysis	ICP-AES (mg/kg)	SPLP (EPA Method 1312)	ICP-AES (mg/kg)	SPLP (EPA Method 1312)	ICP-AES (mg/kg)	ICP-AES (mg/kg)	ICP-AES (mg/kg)	
Analyte		(μg/L)		(μg/L)				
Aluminum	48,000	1,800	42,000	2,000	850			
Antimony					41			
Arsenic	79	30	80 30			50	28	
Barium	390	57	310 27		102			
Beryllium	2	10	2	10	0.23 B			
Cadmium	120	52	140	55	176			
Calcium	1,700	1,300	1,600	1,300	127 B			
Chromium	12	10	8	10	0.42 B			
Cobalt	4	10	4	10	0.21 U			
Copper	1,900	350	1,800	350	1,050			
Iron	45,000	1,200	44,000	770	18,400			
Lead	24,000	8,200		8,100	24,400	908	597	
Magnesium	4,200	3,100	4,000	3,300	24.9 B			
Manganese	3,000	2,400	2,600	2,600	373 J			
Mercury					0.64 J			

Revision: 2 Date: 03/2012 Page 24 of 25

TABLE 2, cont. **Waste Rock Samples**

Sample ID	35B (AM	ILI Mine #35)	35C (AM	LI Mine #35)	CC-SO-06	MMWR01	MMWR02
Sample Source		GS 2007 Faken in 199 7		GS 2007 aken in 1997	UOS START 2009 Sample taken in 1996	STA	ART 2010
Location Description		nd Mogul Rock Pile 3		d Mogul Rock Pile 3	Mogul Mine Waste Rock Pile	Trench at Mogul Mine	Trench at Grand Mogul Mine Pile 3
Analysis Analyte	(mg/kg) Method 1312) (mg/kg) Method 131 (μg/L)		SPLP (EPA Method 1312) (µg/L)	ICP-AES (mg/kg)	ICP-AES (mg/kg)	ICP-AES (mg/kg)	
Molybdenum	36	20	38	20			
Nickel	6	10	6	10	0.21 U		
Phosphorous	1,300	3,900	1,300	3,600			
Potassium	22,000	1,800	19,000	1,700	631 B		
Selenium					5		
Silver	63		64		102		
Sodium	1,700	370	1,400	170	216 B		
Sulfate		81,300		79,900			
Thallium					1.4 B		
Tin	17		18				
Titanium	900	50	800	50			
Vanadium	77	10	75	10	2.2 B		
Zinc	30,000	10,000	34,000	10,000	5800 J	279	565

mg/kg = Milligrams per kilogram μ g/L = Micrograms per Liter B = The analyte was detected in the blank. ^ URS Operating Services, Inc. (UOS). 2009. "Data Gap Analysis – Revision 2 Upper Animas Mining District, Cement Creek" October, 2009.

^{*} U.S. Geological Survey (USGS). 2007. Integrated Investigations of Environmental Effects of Historical Mining in the Animas River Watershed. San Juan County, Colorado Professional Paper 1651.

Revision: 2 Date: 03/2012 Page 25 of 25

Table 3 Chemical Data Analysis - June, 2010

Sample ID	Location Type	Location Description				Dissolved Met	als (μg/l)				Loading	g (lbs/day)	
			Copper	Zinc	Lead	Cadmium	рН	Conductivity (us/cm)	Flow Rate (cfs)	Copper	Zinc	Lead	Cadmium
CC01F	Cement Creek	Basin Flow above of GM	27.2	370	<1.0	1.9	5.72	129	4.61	0.68	9.20		0.05
CC01C	Feature	Waste Seep from Pile 3	295	3210	36.5	14.9	3.45	208					
CC01H	Cement Creek	Basin Flow below GM Piles 2 and 3	141	1120	3	5.5	5.53	134	5.58	4.24	33.71	0.09	0.17
CC01S	Cement Creek	CC at GM between Pile 1 and Pile 2	57.5	1070	2	5.7	5.13	205	2.51	0.78	14.49	0.03	0.08
CC01T	Cement Creek	CC below GM Piles 2 and 3	88.4	978	2.9	5.2	5.27	167	8.26	3.94	43.58	0.13	0.23
CC02i	Feature	GM Pile 1 Drainage above CC	33.7	1290	2.6	4.2	3.92	191	0.016	0.003	0.11	0.0002	0.0004
CC02D	Feature	MM Adit Flow at flume	22.3	22900	153	38.9	3.58	785	0.138	0.02	17.05	0.11	0.03
MMSW03	Feature	MM Adit flow - Mid Waste rock pile	26	19000	15000	33	4.5	814	0.02	0.00	2.05	1.62	0.00
MMSW02	Feature	MM Adit Flow - Toe of Waste Pile	43	20000	8800	33	2.67	820	0.007	0.00	0.76	0.33	0.00
MTD-2	Feature	MM Adit flow at Toe of Waste Rock	529	14900	87.2	37.1	3.02	928					
MTD-1	Feature	Waste Rock Seep Toe of MM Waste Pile	87.9	4400	31	12.2	3.6	248					
MMSW01	Feature	MM Adit and Seep, Toe of MM Waste	590	11000	4900	35	3.82	814	0.02	0.06	1.19	0.53	0.00
MTD-3	Feature	MM drainage above CC	491	8190	45.4	28.9	3.15	604	0.394	1.04	17.41	0.10	0.06
CCOPP-12	Cement Creek	Below M and GM	56.9	731	3.1	3.1	5.07	110	24.5	7.52	96.61	0.41	0.41

QAT = Queen Anne Tributary lbs/day = pounds per day GM = Grand Mogul Mine Shaded Sample ID = EPA sample location

MM = Mogul Mine

 $\begin{array}{ccc} \text{gul Mine} & \text{CC} = \text{Cement Creek} & \mu g/L = M \\ \text{Italics} = \text{Estimated based on flow from previous sampling events.} \end{array}$

 μ g/L = Micrograms per liter

ms/cm (milliSiemens per centimeter)

CFS = Cubic Feet per Second

APPENDIX A Photo Documentation




Photo 1: Mogul Mine Overview.



Photo 2: Mogul Mine adit discharge routed to the south side of the waste rock pile. Note plastic lined channel.





Photo 4: Mogul Pile Lower Tier. Note bedrock Outcrop just below People



Photo 5: Mogul Pile Lower Bench. Water emitting from Lower Tier.



Photo 6: Mogul Lower Tier view east.



Photo 7: Mogul Upper Tier, view south.



Photo 8: View of down valley from top of Mogul Mine piles



Photo 9: Mogul Mine Upper Tier looking east from access road.



Photo 10: Mogul Mine Upper Tier.



Photo 11: Inside Mogul adit.





Photo 13: Up gradient/up valley of potential repository




Photo 14: MMSW01. Below Mogul Mine dump



Photo 15: MMSW02. Below Mogul Toe



Photo 16: MMSW03. South side of tailings.






Photo 18: Unnamed Adit bulkhead and drain. This adit is 500 feet south of the Mogul Mine



Photo 19: Grand Mogul Pile 3. View west, down valley.



Photo 20: Down valley from the top of Grand Mogul Pile 3.





Photo 22: Seep and flow coming from Upper Grand Mogul Pile 3



Photo 23: Up-valley view of the Grand Mogul Pile 2 (Left central picture) and Pile 3 (distant, central picture).



Photo 24: Down-valley view of the Grand Mogul Mine Site. Pile 3 is in the right-foreground, Pile 2 is in the right-central portion.



Photo 25: Grand Mogul Mine Waste Pile 1



Photo 26: Trench at Mogul Mine facing east, mine portal visible in top of picture



Photo 27: Trench at Mogul Mine facing west. Water pooling in lower third of picture is arising from a seep along the edge of the trench closest to the mine portal.



Photo 28: Trench at Mogul Mine Facing East. Water is seeping into trench from eastern end from about 3 feet below ground surface.



Photo 29: Mogul Mine Trench facing east following reinstatement of excavated materials



Photo 30: Mogul Mine Trench 2.



Photo 31: Mogul Mine Trench 2 following reinstatement of excavated materials, Mogul Trench 3 and Grand Mogul Trench 1 were restored to the same condition.



Photo 32: Mogul Mine Trench 3.



Photo 33: Grand Mogul Trench 1



Photo 34: Grand Mogul Trench 2 following reinstatement of excavated materials.



Photo 35: Grand Mogul Trench 2 extending west, no seeps were visible in this reach.



Photo 36: Grand Mogul Trench 2 looking South.



Photo 37: View of Trench 2, discharge is in the fore of the picture talus rock is evident above.